



How to Prepare Wexxar Machinery for Washdown using a Washdown Cover

Instructions for preparing a piece of Wexxar machinery for washdown.

Written By: Wexxar WISE Admin



TOOLS:

- [Washdown Cover](#) (1)

Step 1 — Clean the Machine



- Remove all corrugate dust and fragments.
- (For hot melt machines) Remove any glue residue.

Step 2 — Cover the Machine



- Put the the waterproof cover over the machine.
- Make sure that the cover completely surrounds the machine and reaches all the way to the floor.

Step 3 — Remove the Cover after Washdown



- Wait until the start of the next shift before removing the cover (to allow any condensation enough time to evaporate).
- If there is any water left on the machine, wipe it off with a soft cloth or dry it with compressed air.

Thank you for contacting us. For us to better assist you, please reach out to our technical support by phone at 1.888.565.3219 or 604.930.9300 or by email at Wexxar.Service@promachbuilt.com or Wexxar.Parts@promachbuilt.com along with your machine model and serial number. One of our tech support reps will be glad to answer any questions you may have.